



ATTENTION!

When installing the 36-pin connector to the ThunderMax ECM, apply provided dielectric grease to the inside lip of the ThunderMax ECM (Step 1) to allow the connector rubber weather seal to slide into the housing without rolling or binding. Also apply to the female pin receptacles housed within the clear terminal guide on the 36 pin ECM connector (Step 2). Apply the grease liberally, making sure to cover the entire inside lip and the surface of the terminal pins. This grease will improve vital conductivity between the ThunderMax and the harness connector to reduce pin chaffing and corrosion.